


ARMY RESEARCH LABORATORY



Poisson's Ratio for Cubic Crystals

Arthur Ballato

ARL-TR-425

March 1995



19950421 091

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION IS UNLIMITED.

NOTICES

Disclaimers

The findings in this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

The citation of trade names and names of manufacturers in this report is not to be construed as official Government endorsement or approval of commercial products or services referenced herein.

REPORT DOCUMENTATION PAGE

Form Approved
OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

1. AGENCY USE ONLY (Leave blank)	2. REPORT DATE	3. REPORT TYPE AND DATES COVERED	
	March 1995	Technical Report	
4. TITLE AND SUBTITLE		5. FUNDING NUMBERS	
POISSON'S RATIO FOR CUBIC CRYSTALS			
6. AUTHOR(S)		8. PERFORMING ORGANIZATION REPORT NUMBER	
Arthur Ballato		ARL-TR-425	
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)		9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)	
US Army Research Laboratory (ARL) Electronics and Power Sources Directorate (EPSD) ATTN: AMSRL-EP Fort Monmouth, NJ 07703-5601		10. SPONSORING/MONITORING AGENCY REPORT NUMBER	
11. SUPPLEMENTARY NOTES		12a. DISTRIBUTION/AVAILABILITY STATEMENT	
		12b. DISTRIBUTION CODE	
Approved for public release; distribution is unlimited.			
13. ABSTRACT (Maximum 200 words)		14. SUBJECT TERMS	
General expressions for Poisson's ratio are derived for cubic crystals; simplified forms are given for cases involving symmetry directions.		15. NUMBER OF PAGES	
		14	
		16. PRICE CODE	
		17. SECURITY CLASSIFICATION OF REPORT	
Unclassified		18. SECURITY CLASSIFICATION OF THIS PAGE	
Unclassified		19. SECURITY CLASSIFICATION OF ABSTRACT	
Unclassified		20. LIMITATION OF ABSTRACT	
UL			

Table of Contents

Section	Page
Abstract	1
Introduction	1
Expressions Relating Cubic Stiffnesses and Compliances	2
Definition of Poisson's Ratio for Crystals	2
Relations for Rotated Cubic Compliances - General	3
Single-Axis Rotations	3
Transformation Matrix for General Rotations	4
Poisson's Ratios for Specific Orientations	4
Conclusions	7
Bibliography	8

Accesion For	
NTIS	CRA&I
DTIC	TAB
Unannounced	<input type="checkbox"/>
Justification _____	
By _____	
Distribution / _____	
Availability Codes	
Dist	Avail and / or Special
A-1	

POISSON'S RATIO FOR CUBIC CRYSTALS

Abstract

General expressions for Poisson's ratio are derived for cubic crystals; simplified forms are given for cases involving symmetry directions.

Introduction

Poisson's ratio, ν , is defined for isotropic media as the quotient of lateral contraction to longitudinal extension arising from application of a simple tensile stress; in most materials, this dimensionless number is positive. In crystals, ν takes on different values, depending on the directions of stress and strain chosen. The ratio finds application in a variety of areas of applied elasticity and solid mechanics, for example, as indication of the mechanical coupling between various vibrational modes of motion.

The maximum value of $\nu = +1/2$ is obtained in the incompressible medium limit, where volume is preserved; for ordinary materials, values of $+1/4$ to $+1/3$ are typical, but in crystals ν may vanish, or take on negative values. Analytical formulas for Poisson's ratio are expressed in terms of elastic constants. For the case of crystals of general anisotropy, these expressions are quite unwieldy, but for cubic crystals the symmetry elements reduce the complexity considerably.

Crystals of cubic symmetry include many of the binary semiconductor systems with the piezoelectric zincblende structure, such as GaAs and related alloys. These are extremely important for high technology applications such as cellular radio and microwave collision avoidance radar. All cubic classes have the same elastic matrix scheme, so for our purposes it is not necessary to distinguish between the cubic point groups. The cubic elastic matrix scheme is identical in form to that of isotropic substances; the difference is that for isotropic materials the shear coefficient (s_{44} or c_{44}) is related to the two other independent coefficients, whereas in cubic crystals it is a third independent quantity.

Expressions Relating Cubic Stiffnesses and Compliances

Relations for Poisson's ratio are most simply expressed in terms of the elastic compliances $[s_{\lambda\mu}]$. It is often the case, however, that the most accurate determinations of the elastic constants (resonator and transit-time methods) yield values for the stiffnesses $[c_{\lambda\mu}]$ directly; the conversion relations are given below. For the cubic system, the elastic stiffness and compliance matrices have identical form. Referred to the [100], [010], and [001] directions, the matrices are:

$$\begin{array}{cccccc} c_{11} & c_{12} & c_{12} & 0 & 0 & 0 \\ c_{12} & c_{11} & c_{12} & 0 & 0 & 0 \\ c_{12} & c_{12} & c_{11} & 0 & 0 & 0 \\ 0 & 0 & 0 & c_{44} & 0 & 0 \\ 0 & 0 & 0 & 0 & c_{44} & 0 \\ 0 & 0 & 0 & 0 & 0 & c_{44} \end{array} \quad \begin{array}{cccccc} s_{11} & s_{12} & s_{12} & 0 & 0 & 0 \\ s_{12} & s_{11} & s_{12} & 0 & 0 & 0 \\ s_{12} & s_{12} & s_{11} & 0 & 0 & 0 \\ 0 & 0 & 0 & s_{44} & 0 & 0 \\ 0 & 0 & 0 & 0 & s_{44} & 0 \\ 0 & 0 & 0 & 0 & 0 & s_{44} \end{array}$$

Stiffness and compliance are matrix reciprocals; the three independent components of each are related by:

$$c_{11} = (s_{11} + s_{12}) / [(s_{11} - s_{12})(s_{11} + 2s_{12})]$$

$$c_{12} = (-s_{12}) / [(s_{11} - s_{12})(s_{11} + 2s_{12})]$$

$$c_{44} = 1 / s_{44}$$

These are inverted simply by an interchange of symbols $c_{\lambda\mu}$ and $s_{\lambda\mu}$. For the case of isotropy, one has the further relations $s_{44} = 2(s_{11} - s_{12})$ and $c_{44} = (c_{11} - c_{12})/2$. For cubic crystals, anisotropy factors $s = (s_{11} - s_{12} - s_{44}/2)$ and $c = (c_{11} - c_{12} - 2c_{44})$ are defined, in terms of which the departure from isotropy may be quantized. The Poisson's ratios are simply expressed in terms of s_{11} , s_{12} , and s .

Definition of Poisson's Ratio for Crystals

Poisson's ratio for crystals is defined in general as $v_{ji} = s_{ij}' / s_{jj}'$, where x_j is the direction of the longitudinal extension, x_i is the direction of the accompanying lateral contraction, and the s_{ij}' and s_{jj}' are the appropriate elastic compliances referred to this right-handed axial set. It suffices to take x_1 as the direction of the longitudinal extension; then two Poisson's ratios are defined by the orientations of the lateral axes x_2 and x_3 : $v_{21} = s_{12}' / s_{11}'$ and $v_{31} = s_{13}' / s_{11}'$. Application of the definition requires

specification of the orientation of the x_k coordinate set with respect to the crystallographic directions, and transformation of the compliances accordingly.

Relations for Rotated Cubic Compliances - General

The unprimed compliances s_{11} , s_{44} , and s_{12} are referred to a set of right-handed cubic crystallographic axes aligned with the [100], [010], and [001] directions. Direction cosines a_{mn} relate the transformation from these axes to the set specifying the directions of the longitudinal extension (x_1), and the lateral contractions (x_2 and x_3). General expressions for the transformed compliances that enter the formulas for v_{21} and v_{31} are:

$$s_{11}' = s_{11} [a_{11}^4 + a_{12}^4 + a_{13}^4] + (s_{44} + 2 s_{12}) [a_{11}^2 a_{12}^2 + a_{12}^2 a_{13}^2 + a_{13}^2 a_{11}^2]$$

$$s_{12}' = s_{11} [a_{11}^2 a_{21}^2 + a_{12}^2 a_{22}^2 + a_{13}^2 a_{23}^2] + \\ s_{44} [a_{12} a_{13} a_{22} a_{23} + a_{13} a_{11} a_{23} a_{21} + a_{11} a_{12} a_{21} a_{22}] + \\ s_{12} [a_{11}^2 a_{22}^2 + a_{12}^2 a_{21}^2 + a_{11}^2 a_{23}^2 + a_{13}^2 a_{21}^2 + a_{12}^2 a_{23}^2 + a_{13}^2 a_{22}^2]$$

$$s_{13}' = s_{11} [a_{11}^2 a_{31}^2 + a_{12}^2 a_{32}^2 + a_{13}^2 a_{33}^2] + \\ s_{44} [a_{12} a_{13} a_{32} a_{33} + a_{13} a_{11} a_{33} a_{31} + a_{11} a_{12} a_{31} a_{32}] + \\ s_{12} [a_{11}^2 a_{32}^2 + a_{12}^2 a_{31}^2 + a_{11}^2 a_{33}^2 + a_{13}^2 a_{31}^2 + a_{12}^2 a_{33}^2 + a_{13}^2 a_{32}^2]$$

Single-Axis Rotations

The general rotation relations given above for s_{11}' , s_{12}' , and s_{13}' simplify considerably for single-axis rotations, and use of the anisotropy factor $s = (s_{11} - s_{12} - s_{44}/2)$. Longitudinal extension is along the x_1 axis, and abbreviations $c(\phi)$ and $s(\phi)$ stand for $\cos(\phi)$ and $\sin(\phi)$, etc.:

(A) **Rotation about x_1 :** $s_{11}' = s_{11}$; $s_{12}' = s_{13}' = s_{12}$; $v_{21} = v_{31} = s_{12} / s_{11}$

(B) **Rotation about x_2 :** $s_{11}' = s_{11} - 2 s [c^2(\psi) s^2(\psi)]$; $s_{12}' = s_{12}$

$$s_{13}' = s_{12} + 2 s [c^2(\psi) s^2(\psi)]; v_{21} = s_{12} / s_{11}'; v_{31} = s_{13}' / s_{11}'$$

(C) **Rotation about x_3 :** $s_{11}' = s_{11} - 2 s [c^2(\phi) s^2(\phi)]$

$$s_{12}' = s_{12} + 2 s [c^2(\phi) s^2(\phi)]; s_{13}' = s_{12}; v_{21} = s_{12}' / s_{11}'; v_{31} = s_{12} / s_{11}'$$

Transformation Matrix for General Rotations

In order to derive the Poisson's ratio for the most general case, we consider the transformation matrix for a combination of three coordinate rotations: a first rotation about x_3 by angle ϕ , a second rotation about the new x_1 by angle θ , and a third rotation about the resulting x_2 by angle ψ . When these angles are set to zero, the x_1 , x_2 , x_3 axes coincide respectively with the [100], [010], and [001] crystallographic directions. For nonzero angles, the direction cosines a_{mn} are as follows:

$$\begin{bmatrix} [c(\phi)c(\psi) - s(\phi)s(\theta)s(\psi)] & [s(\phi)c(\psi) + c(\phi)s(\theta)s(\psi)] & [-c(\theta)s(\psi)] \\ [-s(\phi)c(\theta)] & [c(\phi)c(\theta)] & [s(\theta)] \\ [c(\phi)s(\psi) + s(\phi)s(\theta)c(\psi)] & [s(\phi)s(\psi) - c(\phi)s(\theta)c(\psi)] & [c(\theta)c(\psi)] \end{bmatrix}$$

Substitution of these a_{mn} into the expressions for s_{11}' , s_{12}' , and s_{13}' , and thence into the formulas $v_{21} = s_{12}' / s_{11}'$ and $v_{31} = s_{13}' / s_{11}'$ formally solves the problem for specified values of ϕ , θ , and ψ .

Poisson's Ratios for Specific Orientations

- 1) Longitudinal extension along [100]: $\phi = \psi = 0$; θ arbitrary. This is the same as case (A) above. $v_{21} = v_{31} = s_{12} / s_{11}$, independent of angle θ .
- 2) Longitudinal extension along an axis normal to [001]: $\psi = 0$; ϕ and θ arbitrary. Direction cosines are:

$$\begin{bmatrix} [c(\phi)] & [s(\phi)] & [0] \\ [-s(\phi)c(\theta)] & [c(\phi)c(\theta)] & [s(\theta)] \\ [s(\phi)s(\theta)] & [-c(\phi)s(\theta)] & [c(\theta)] \end{bmatrix}$$

Rotated compliances are:

$$s_{11}' = s_{11} - 2s [c^2(\phi) s^2(\phi)]$$

$$s_{12}' = s_{12} + 2s [c^2(\phi) s^2(\phi) c^2(\theta)]$$

$$s_{13}' = s_{12} + 2s [c^2(\phi) s^2(\phi) s^2(\theta)]$$

$$v_{21} = s_{12}' / s_{11}' ; v_{31} = s_{13}' / s_{11}'$$

2a) When both θ and $\psi = 0$, but ϕ is arbitrary, this reduces to case (C) above:

$$s_{11}' = s_{11} - 2s [c^2(\phi) s^2(\phi)]$$

$$s_{12}' = s_{12} + 2s [c^2(\phi) s^2(\phi)]$$

$$s_{13}' = s_{12} ; v_{21} = s_{12}' / s_{11}' ; v_{31} = s_{12} / s_{11}'$$

2b) When $\phi = \pi/4$, θ is arbitrary, and $\psi = 0$, the x_1 axis (direction of longitudinal extension) coincides with the [110] direction; the rotated compliances become:

$$s_{11}' = s_{11} - s (1/2) ; s_{12}' = s_{12} + s (1/2)[c^2(\theta)] ; s_{13}' = s_{12} + s (1/2)[s^2(\theta)]$$

$$v_{21} = s_{12}' / s_{11}' = (2s_{12} + s [c^2(\theta)]) / (2s_{11} - s)$$

$$v_{31} = s_{13}' / s_{11}' = (2s_{12} + s [s^2(\theta)]) / (2s_{11} - s)$$

2c) When $\phi = \pi/4$, $\theta = 0$, and $\psi = 0$, the x_1 axis (direction of longitudinal extension) coincides with the [110] direction, and the x_2 and x_3 axes coincide respectively with the [-110] and [001] directions. The rotated compliances then become:

$$s_{11}' = s_{11} - s (1/2) ; s_{12}' = s_{12} + s (1/2) ; s_{13}' = s_{12}$$

The Poisson's ratios are thus:

$$v_{21} = s_{12}' / s_{11}' = (2s_{12} + s) / (2s_{11} - s) \text{ and}$$

$$v_{31} = s_{13}' / s_{11}' = (2s_{12}) / (2s_{11} - s)$$

When $\theta = \pi/2$ instead of 0, v_{21} and v_{31} are simply interchanged.

3) Longitudinal extension in the plane containing [110] and [111]:
 $\phi = \pi/4$, $\theta = 0$, ψ arbitrary. The x_2 axis coincides with the [-110] direction. Direction cosines are:

$c(\psi)/\sqrt{2}$	$c(\psi)/\sqrt{2}$	$-s(\psi)$
-1/\sqrt{2}	1/\sqrt{2}	0
$s(\psi)/\sqrt{2}$	$s(\psi)/\sqrt{2}$	$c(\psi)$

Rotated compliances are:

$$s_{11}' = s_{11} - 2 s [c^2(\psi)] [1 - (3/4)c^2(\psi)]$$

$$s_{12}' = s_{12} + (1/2) s [c^2(\psi)]$$

$$s_{13}' = s_{12} + (3/2) s [c^2(\psi) s^2(\psi)]$$

The Poisson's ratios are: $\nu_{21} = s_{12}' / s_{11}'$; $\nu_{31} = s_{13}' / s_{11}'$. When $\psi = 0$, this reduces to case 2c) above; when $\psi = \pi/2$, it is equivalent to case (A) with extension along [001].

4) Longitudinal extension along [-11-1]: $\phi = \pi/4$, $\theta = 0$, and $\psi = \text{arc sin } (1/\sqrt{3})$. The x_2 and x_3 axes coincide, respectively, with the [-110] and [112] directions. Direction cosines a_{mn} are:

$$\begin{array}{lll} 1/\sqrt{3} & 1/\sqrt{3} & -1/\sqrt{3} \\ -1/\sqrt{2} & 1/\sqrt{2} & 0 \\ 1/\sqrt{6} & 1/\sqrt{6} & \sqrt{(2/3)} \end{array}$$

Rotated compliances are:

$$s_{11}' = s_{11} - (2/3) s$$

$$s_{12}' = s_{13}' = s_{12} + (1/3) s$$

The Poisson's ratios are: $\nu_{21} = \nu_{31} = s_{12}' / s_{11}' = (3 s_{12} + s) / (3 s_{11} - 2 s)$

5) Longitudinal extension along [-11-1]: $\phi = \pi/4$ and $\psi = \text{arc sin } (1/\sqrt{3})$. Provision is made for rotating the lateral axes by adding a third rotation, about the resulting x_1 (i.e., about [-11-1]), by angle θ , subsequent to the ϕ and ψ rotations.

Direction cosines a_{mn} are now:

$$\begin{array}{lll} 1/\sqrt{3} & 1/\sqrt{3} & -1/\sqrt{3} \\ 1/\sqrt{2} [-c(\theta) + s(\theta)/\sqrt{3}] & 1/\sqrt{2} [c(\theta) + s(\theta)/\sqrt{3}] & \sqrt{(2/3)} s(\theta) \\ 1/\sqrt{2} [s(\theta) + c(\theta)/\sqrt{3}] & 1/\sqrt{2} [-s(\theta) + c(\theta)/\sqrt{3}] & \sqrt{(2/3)} c(\theta) \end{array}$$

Rotated compliances computed from these direction cosines turn out to be independent of angle θ , and are identical to those of case 4) above:

$$s_{11}' = s_{11} - (2/3) s$$

$$s_{12}' = s_{13}' = s_{12} + (1/3) s$$

The Poisson's ratios are: $\nu_{21} = \nu_{31} = s_{12}' / s_{11}' = (3 s_{12} + s) / (3 s_{11} - 2 s)$

Conclusions

Poisson's ratio, with respect to rotated coordinate axes for cubic materials, has been obtained. Three cases are of particular interest:

- For longitudinal extension along [100] (along the cube axis), $\nu_{21} = \nu_{31} = s_{12} / s_{11}$, independent of lateral directions. Case (A).
- For longitudinal extension along [110] (along the face diagonal; normal to the dodecahedral planes (110)), with $s = (s_{11} - s_{12} - s_{44}/2)$,

$$\nu_{21} = (2 s_{12} + s [c^2(\theta)]) / (2 s_{11} - s)$$

$$\nu_{31} = (2 s_{12} + s [s^2(\theta)]) / (2 s_{11} - s)$$

When $\theta = 0$, the x_2 and x_3 axes coincide, respectively, with the [-110] and [001] directions. Case 2c). Poisson's ratios are:

$$\nu_{21} = (2 s_{12} + s) / (2 s_{11} - s)$$

$$\nu_{31} = (2 s_{12}) / (2 s_{11} - s)$$

- For longitudinal extension along [111] (along the body diagonal; normal to the octahedral planes (111)). Case 5). Poisson's ratios are independent of the lateral directions:

$$\nu_{21} = \nu_{31} = [3 s_{12} + s] / [3 s_{11} - 2 s]$$

Bibliography

- [1] W G Cady, Piezoelectricity, McGraw-Hill, New York, 1946; Dover, New York, 1964.
- [2] J F Nye, Physical Properties of Crystals, Clarendon Press, Oxford, 1957; Oxford University Press, 1985.
- [3] R F S Hearmon, An Introduction to Applied Anisotropic Elasticity, Oxford University Press, 1961.
- [4] M J P Musgrave, Crystal Acoustics, Holden-Day, San Francisco, 1970.

ARMY RESEARCH LABORATORY
ELECTRONICS AND POWER SOURCES DIRECTORATE
CONTRACT OR IN-HOUSE TECHNICAL REPORTS
MANDATORY DISTRIBUTION LIST

February 1995
Page 1 of 2

Defense Technical Information Center*
ATTN: DTIC-OCC
Cameron Station (Bldg 5)
Alexandria, VA 22304-6145
(*Note: Two copies will be sent from
STINFO office, Fort Monmouth, NJ)

Director
US Army Material Systems Analysis Actv
ATTN: DRXSY-MP
(1) Aberdeen Proving Ground, MD 21005

Commander, AMC
ATTN: AMCDE-SC
5001 Eisenhower Ave.
(1) Alexandria, VA 22333-0001

Director
Army Research Laboratory
ATTN: AMSRL-D (John W. Lyons)
2800 Powder Mill Road
(1) Adelphi, MD 20783-1145

Director
Army Research Laboratory
ATTN: AMSRL-DD (COL Thomas A. Dunn)
2800 Powder Mill Road
(1) Adelphi, MD 20783-1145

Director
Army Research Laboratory
2800 Powder Mill Road
Adelphi, MD 20783-1145
(1) AMSRL-OP-SD-TA (ARL Records Mgt)
(1) AMSRL-OP-SD-TL (ARL Tech Library)
(1) AMSRL-OP-SD-TP (ARL Tech Publ Br)

Directorate Executive
Army Research Laboratory
Electronics and Power Sources Directorate
Fort Monmouth, NJ 07703-5601
(1) AMSRL-EP
(1) AMSRL-EP-T (M. Hayes)
(1) AMSRL-OP-RM-FM
(22) Originating Office

Advisory Group on Electron Devices
ATTN: Documents
2011 Crystal Drive, Suite 307
(2) Arlington, VA 22202

Commander, CECOM
R&D Technical Library
Fort Monmouth, NJ 07703-5703
(1) AMSEL-IM-BM-I-L-R (Tech Library)
(3) AMSEL-IM-BM-I-L-R (STINFO ofc)

Director, Army Research Laboratory
2800 Powder Mill Road
Adelphi, MD 20783-1145
(1) AMSRL-OP-SD-TP (Debbie Lehtinen)

ARMY RESEARCH LABORATORY
ELECTRONICS AND POWER SOURCES DIRECTORATE
SUPPLEMENTAL DISTRIBUTION LIST
(ELECTIVE)

February 1995
Page 2 of 2

(1) Deputy for Science & Technology
Office, Asst Sec Army (R&D)
Washington, DC 20310

Cdr, Marine Corps Liaison Office
ATTN: AMSEL-LN-MC
Fort Monmouth, NJ 07703-5033

(1) HQDA (DAMA-ARZ-D/
Dr. F.D. Verderame)
Washington, DC 20310

Director
Naval Research Laboratory
ATTN: Code 2627
(1) Washington, DC 20375-5000

USAF Rome Laboratory
Technical Library, FL2810
ATTN: Documents Library
Corridor W, STE 262, RL/SUL
26 Electronics Parkway, Bldg 106
Griffiss Air Force Base
(1) NY 13441-4514

Dir, ARL Battlefield
Environment Directorate
ATTN: AMSRL-BE
White Sands Missile Range
(1) NM 88002-5501

Dir, ARL Sensors, Signatures,
Signal & Information Processing
Directorate (S3I)
ATTN: AMSRL-SS
2800 Powder Mill Road
(1) Adelphi, MD 20783-1145

Dir, CECOM Night Vision/
Electronic Sensors Directorate
ATTN: AMSEL-RD-NV-D
(1) Fort Belvoir, VA 22060-5677

Dir, CECOM Intelligence and
Electronic Warfare Directorate
ATTN: AMSEL-RD-IEW-D
Vint Hill Farms Station
(1) Warrenton, VA 22186-5100